

VIN:

Vehicle:

System Version:

Data Version:

---

00 40 13 (044)

## Front/rear brake service - deletion of CBS display on MINI F56

### Situation:

On the MINI F56, the CBS display of the front and rear brake service is discontinued. There is no transmission of remaining distance data to the ignition key, i.e. display of the remaining distance and when due in ISPA/ISPA light are discontinued. However, the scope of maintenance work for the front brake and rear brake can be selected manually for the repair order.

The customer is no longer able to access the remaining distance in the central information display. A due brake pad change is displayed to the customer by the red warning light after the brake pad wear sensor has been sanded.

The pad thickness for determination of the remaining distance must be measured manually. The check is made at every service visit.

**Vehicles concerned:** MINI F56

### Procedure:

#### Standard scope of service

=> The brake pad thickness is to be checked on the front axle and rear axle at every service visit.

#### Front/rear brake service

=> Reset of the CBS display for the front and rear brake service is discontinued.